Accomplishment Number DT00258

Accomplishment Date 15/10/2021

Inspection Number LOW

Defect Number DN22334

Incident Number No data

Work Order Number No data

Planned Work Number No data

Completed True

Latitude -24.9794285912925

Longitude 152.183387707455

Primary Location Baldwins Road, 2683

her Right to Information Act 2009 Location South Bingera Road to Baldwins Road CH 600

Sub Location No data

Chainage From 598.0000

Chainage To 0.0000

Lane Code No data

Carriageway Number No data

Work Team PRIVATE CONTRACTOR

Work Team Size 1.0000

Work Group 2109

Activity 1407

Quantity Accomplished 5.0000

Second Qty Accomplished No data

Third Qty Accomplished No data

Fourth Qty Accomplished No data

Payment Type No data

Time Worked 1.0000

Comments Please poison roadside furniture on this road.

Compliance True

UDS Exceeded False

Job Safety Analysis True

Warranty Required False

External Reference Roadside Spraying Program

TCP No data

27/05/2022, 08:50

Job Number W21472.2109

Ordered Work False

ARN No data

Work Group Description Roadside Vegetation

Activity Name Herbicide Spraying

Activity Group Roadside

Activity Type Roadside Vegetation

Defect Group 11 - Roadside Vegetation Defects

Defect Type Vegetation Growth on Medians

Defect Code NL4 R

Primary Location Description No data

Location Description Childers Maintenance Area

ved **Additional Comments** Has been completed by contractors while spraying Pine Creek Area Active Weed **Busters**

Non Compliance Reason No data

Location Zone No data

Rate 0.0000

Warranty Expiry Date No data

Estimated Cost 0.0000

Approximate Location False

Lane Code Description No data

Funding Category No data

under Right **Funding Category Description** No data

Element Number No data

Element Description No data

Network Schedule No data

Network Schedule Description No data

Work Type No data

Request Number No data

Electronic Form Number No data

Electronic Form Name No data

Location Sequence No data

Start Time 07:36

Finish Time 08:36

Claim Number No data

Released under Right to Information Act 2000

Accomplishment Number AC08234 Accomplishment Date 28/02/2022 Inspection Number No data **Defect Number** No data Incident Number No data Work Order Number No data **Planned Work Number** Google No data Completed **Photos** True Latitude -24.979157 Longitude 152.188605 **Primary Location** South Bingera Road, 3101 Location Cedars Road to South Bingera Road CH 1140 Sub Location No data **Chainage From** 1940.0000 [No Caption] **Chainage To** 26.0000 ndereight Lane Code No data **Carriageway Number** No data Work Team 305 - CHILDERS SLASHER Work Team Size 1.0000 Work Group 2109 Activity 1401 **Quantity Accomplished** 1.0000 Second Qty Accomplished No data Third Qty Accomplished No data

Fourth Qty Accomplished No data

Payment Type No data

Time Worked 6.0000

Comments No data

Compliance True


UDS Exceeded False

Job Safety Analysis True

Warranty Required False

External Reference No data

тср No data



07/06/2022, 09:59

Job Number W23591.2109

Ordered Work False

ARN No data

Work Group Description Roadside Vegetation

Activity Name Tractor Slashing

Activity Group Roadside

Activity Type Roadside Vegetation

Defect Group No data

Defect Type No data

Defect Code No data

Primary Location Description No data

Location Description Childers Maintenance Area

Additional Comments No data

Non Compliance Reason No data

Location Zone No data

Rate 492.6000

Warranty Expiry Date No data

Estimated Cost 492.6000

Approximate Location No data

Lane Code Description No data

Funding Category No data

Funding Category Description No data

Element Number No data

Element Description No data

Network Schedule No data

n under Right to Internation Act 2009 **Network Schedule Description** No data

Work Type No data

Request Number No data

Electronic Form Number No data

Electronic Form Name No data

Location Sequence No data

Start Time No data

Finish Time No data

Claim Number No data

BUNDABERG ROADS 1819 - Accomplishment Details

Released under Right to Information Act 2000



07/06/2022, 09:46

Job Number W21472.2100

Ordered Work False

ARN No data

Work Group Description **Bituminous Patching/Sealing**

Activity Name Pothole Patching

Activity Group Sealed Surfaces

on the Right of the Inder Right Activity Type **Bituminous Patching/Sealing**

Defect Group No data

Defect Type No data

Defect Code No data

Primary Location Description No data

Location Description Childers Maintenance Area

Additional Comments No data

Non Compliance Reason No data

Location Zone No data

Rate 669.6867

Warranty Expiry Date No data

Estimated Cost 66.9687

Approximate Location False

Lane Code Description No data

Funding Category No data

Funding Category Description No data

Element Number No data

Element Description No data

Network Schedule No data

Network Schedule Description No data

Work Type No data

Request Number No data

Electronic Form Number No data

Electronic Form Name No data

Location Sequence No data

Start Time 10:52

Finish Time 11:12

Claim Number No data

BUNDABERG ROADS 1819 - Accomplishment Details

Released under Right to Information Act 2000

Accomplishment	Number
CB01032	

Accomplishment Date 11/10/2021

Inspection Number No data

Defect Number No data

Incident Number No data

Work Order Number No data

Planned Work Number No data

Completed True

Latitude No data

Longitude No data

Primary Location South Bingera Road, 3101

Inder Right to Information Act 2009 Location Cedars Road to South Bingera Road CH 1140

Sub Location No data

Chainage From 0.0000

Chainage To 3159.0000

Lane Code No data

Carriageway Number No data

Work Team 305 - CHILDERS SLASHER

Work Team Size 1.0000

Work Group 2109

Activity 1401

Quantity Accomplished 1.0000

Second Qty Accomplished No data

Third Qty Accomplished No data

Fourth Qty Accomplished No data

Payment Type No data

Time Worked 4.0000

Comments Tractor slashing

Compliance True

UDS Exceeded False

Job Safety Analysis True

Warranty Required False

External Reference No data

тср No data

07/06/2022, 09:53

Job Number W23591.2109

Ordered Work False

ARN No data

Work Group Description Roadside Vegetation

Activity Name Tractor Slashing

Activity Group Roadside

Activity Type Roadside Vegetation

Defect Group No data

Defect Type No data

Defect Code No data

Primary Location Description No data

Location Description Childers Maintenance Area

Additional Comments No data

Non Compliance Reason No data

Location Zone No data

Rate 328.4000

Warranty Expiry Date No data

Estimated Cost 328.4000

Approximate Location False

Lane Code Description No data

Funding Category No data

Funding Category Description No data

Element Number No data

Element Description No data

Network Schedule No data

tor under Right **Network Schedule Description** No data

Work Type No data

Request Number No data

Electronic Form Number No data

Electronic Form Name No data

Location Sequence No data

Start Time 05:17

Finish Time 09:17

Claim Number No data

Released under Right to Information Act 2000

Accomplishment Number CB01033	
Accomplishment Date 11/10/2021	
Inspection Number No data	
Defect Number No data	
Incident Number No data	
Work Order Number No data	
Planned Work Number No data	05
Completed True	
Latitude No data	
Longitude No data	
Primary Location Baldwins Road, 2683	10
Location Baldwins Road CH 600 to CH 872	× O
Sub Location No data	
Chainage From 0.0000	
Chainage To 871.0000	
Lane Code No data	
Carriageway Number No data	
Work Team 305 - CHILDERS SLASHER	
Work Team Size 1.0000	
Work Group 2109	
Activity 1401	
2109 Activity 1401 Quantity Accomplished 1.0000 Second Qty Accomplished	
Second Qty Accomplished No data	
Third Qty Accomplished No data	
Fourth Qty Accomplished No data	
Payment Type No data	
Time Worked 0.5000	
Comments Tractor slashing	
Compliance True	
UDS Exceeded False	
Job Safety Analysis True	
Warranty Required False	
External Reference No data	
TCP No data	

07/06/2022, 09:55

Job Number W21472.2109

Ordered Work False

ARN No data

Work Group Description Roadside Vegetation

Activity Name Tractor Slashing

Activity Group Roadside

Activity Type Roadside Vegetation

Defect Group No data

Defect Type No data

Defect Code No data

Primary Location Description No data

Location Description Childers Maintenance Area

Additional Comments No data

Non Compliance Reason No data

Location Zone No data

Rate 41.0500

Warranty Expiry Date No data

Estimated Cost 41.0500

Approximate Location False

Lane Code Description No data

Funding Category No data

Funding Category Description No data

Element Number No data

Element Description No data

Network Schedule No data

to under Right **Network Schedule Description** No data

Work Type No data

Request Number No data

Electronic Form Number No data

Electronic Form Name No data

Location Sequence No data

Start Time 08:49

Finish Time 09:19

Claim Number No data

BUNDABERG ROADS 1819 - Accomplishment Details

Released under Right to Information Act 2000

Accomplishment	Number
CB01119	

Accomplishment Date 15/12/2021

Inspection Number No data

Defect Number No data

Incident Number No data

Work Order Number No data

Planned Work Number No data

Completed True

Latitude No data

Longitude No data

Primary Location South Bingera Road, 3101

Inder Right to Information Act 2009 Location Cedars Road to South Bingera Road CH 1140

Sub Location No data

Chainage From 0.0000

Chainage To 2547.0000

Lane Code No data

Carriageway Number No data

Work Team **PRIVATE CONTRACTOR**

Work Team Size 1.0000

Work Group 2109

Activity 1401

Quantity Accomplished 1.0000

Second Qty Accomplished No data

Third Qty Accomplished No data

Fourth Qty Accomplished No data

Payment Type No data

Time Worked 4.0000

Comments Tractor slashing

Compliance True

UDS Exceeded False

Job Safety Analysis True

Warranty Required False

External Reference No data

тср No data

07/06/2022, 09:57

Job Number W23591.2109

Ordered Work False

ARN No data

Work Group Description Roadside Vegetation

Activity Name Tractor Slashing

Activity Group Roadside

Activity Type **Roadside Vegetation**

Defect Group No data

Defect Type No data

Defect Code No data

Primary Location Description No data

Location Description Childers Maintenance Area

Additional Comments No data

Non Compliance Reason No data

Location Zone No data

Rate 374.0000

Warranty Expiry Date No data

Estimated Cost 374.0000

Approximate Location False

Lane Code Description No data

Funding Category No data

Funding Category Description No data

Element Number No data

Element Description No data

Network Schedule No data

on under Right **Network Schedule Description** No data

Work Type No data

Request Number No data

Electronic Form Number No data

Electronic Form Name No data

Location Sequence No data

Start Time 07:16

Finish Time 11:16

Claim Number No data

Released under Right to Information Act 2000



Inspection Number LOW

Defect Number DN22334

Incident Number No data

Work Order Number No data

Planned Work Number No data

Completed True

Latitude -24.9794285912925

Longitude 152.183387707455

Primary Location Baldwins Road, 2683

Location South Bingera Road to Baldwins Road CH 600

Sub Location No data

Chainage From 598.0000

Chainage To 0.0000

Lane Code No data

Carriageway Number No data

Work Team PRIVATE CONTRACTOR

Work Team Size 1.0000

Work Group 2109

Activity 1407

Quantity Accomplished 5.0000

Second Qty Accomplished No data

Third Qty Accomplished No data

Fourth Qty Accomplished No data

Payment Type No data

Time Worked 1.0000

Comments Please poison roadside furniture on this road.

Compliance True

UDS Exceeded False

Job Safety Analysis True

Warranty Required False

External Reference Roadside Spraying Program

TCP No data

Cedars RO DT00258 R aldwins Rd s Bingera Creek Her Right to Information Act Google Map data ©2022

07/06/2022, 10:01

Job Number W21472.2109

Ordered Work False

ARN No data

Work Group Description Roadside Vegetation

Activity Name Herbicide Spraying

Activity Group Roadside

Activity Type Roadside Vegetation

Defect Group 11 - Roadside Vegetation Defects

Defect Type Vegetation Growth on Medians

Defect Code NL4 R

Primary Location Description No data

Location Description Childers Maintenance Area

.ved **Additional Comments** Has been completed by contractors while spraying Pine Creek Area Active Weed **Busters**

Non Compliance Reason No data

Location Zone No data

Rate 0.0000

Warranty Expiry Date No data

Estimated Cost 0.0000

Approximate Location False

Lane Code Description No data

Funding Category No data

underRight **Funding Category Description** No data

Element Number No data

Element Description No data

Network Schedule No data

Network Schedule Description No data

Work Type No data

Request Number No data

Electronic Form Number No data

Electronic Form Name No data

Location Sequence No data

Start Time 07:36

Finish Time 08:36

Claim Number No data

Released under Right to Information Act 2000

RB00381	
Accomplishment Date 04/03/2022	
Inspection Number No data	
Defect Number No data	
Incident Number No data	
Work Order Number No data	
Planned Work Number No data	
Completed True	
Latitude No data	<u> </u>
Longitude No data	
Primary Location South Bingera Road, 3101	
Location South Bingera Road, 3101	× O
Sub Location No data	
Chainage From 10.0000	
Chainage To 3100.0000	
Lane Code No data	
Carriageway Number No data	
Work Team WJM EXCAVATIONS - DRAINAGE	
Work Team Size 2.0000	
Work Group 2102	
Activity 1200	
2102 Activity 1200 Quantity Accomplished 1.0000 Second Qty Accomplished	
Second Qty Accomplished No data	
Third Qty Accomplished No data	
Fourth Qty Accomplished No data	
Payment Type No data	
Time Worked 9.5000	
Comments Repairs after flood event.	
Compliance True	
UDS Exceeded False	
Job Safety Analysis True	
Warranty Required False	
External Reference No data	
TCP No data	

07/06/2022, 09:51

Job Number W23591.2102

Ordered Work False

ARN No data

Work Group Description Pavement Repairs

Activity Name Emergency Road Works

Activity Group Unsealed Surfaces

Activity Type **Pavement Repairs**

Defect Group No data

Defect Type No data

Defect Code No data

Primary Location Description No data

Location Description Childers Maintenance Area

Additional Comments No data

Non Compliance Reason No data

Location Zone No data

Rate 14603.2700

Warranty Expiry Date No data

Estimated Cost 14603.2700

Approximate Location False

Lane Code Description No data

Funding Category No data

Funding Category Description No data

Element Number No data

Element Description No data

Network Schedule No data

with the product of t **Network Schedule Description** No data

Work Type No data

Request Number No data

Electronic Form Number No data

Electronic Form Name No data

Location Sequence No data

Start Time 01:40

Finish Time 11:10

Claim Number No data

BUNDABERG ROADS 1819 - Accomplishment Details

Released under Right to Mormation Act 2000

DN22334

G

Google

hio mailon ho

aldwins Rd

Cedars.

Rd

Map data ©2022

Defect Number DN22334

Request Number No data

Incident Number No data

Inspection Number LOW

Work Order Number No data

Planned Work Number No data

Electronic Form Number No data

Inspection Type No data

Inspection Direction No data

Date Raised 25/09/2020

Raised By Bryan Porter

Primary Location Baldwins Road, 2683

Location South Bingera Road to Baldwins Road CH 600

Sub Location No data

Chainage From 598,0000

Chainage To 0.0000

Lane Code No data

Carriageway Number No data

Location Category D

Defect Code NL4 R

Defect Group 11 - Roadside Vegetation Defects

Defect Type Vegetation Growth on Medians

Position within Location Low asset deterioration (asset has deteriorated slightly from its original design)

<i><i>k^{*i*}

Physical Description Grass in rural areas > 500 mm

Estimated Quantity 5.0000

Second Quantity No data

Third Quantity No data

Fourth Quantity No data

Activity 1407


Activity Group Roadside

Work Group 2109

Work Team 405

Response Time 0.0000

Defect Score 10.0000



07/06/2022, 10:07

Priority 2 - Ordered Work

Risk Assessment No data

Status ASSIGNED

Target Date No data

Comments Please poison roadside furniture on this road.

ТСР No data

Completion Date 15/10/2021

Cause Of Defect No data

Long Term False

Job Number W21472.2109

External Reference Roadside Spraying Program

Intervention Standard No data

Estimated Cost No data

Funding Element No data

Responsibility Email No data

Released under Right Initial Accomplishment Date

BUNDABERG_ROADS_1819 - Defect Details

Information Act 2009

Customer Request Management Enquiry 618985/2021 - Corridor Management - Public Utility Plant (Applications, Notifications)

Received Date	26/08/2021 11:26 AM
Determination Details	07/09/2021 02:04 PM Completed (COMP)
Public Reference ID	2008724
Contact Method	EMAIL
Description	Written Agreement for Proposed Works - Ergon - ERDS - WR1635352 - Baldwins Road, South Bingera Road, Cedarview Lane and Old Cedar Road, South isis
Creation Officer	P E Schofield
Last Modified By	P E Schofield
Мар	
Click for interactive	
Workflow	derRies
Workflow Summary	
Task name	Corridor Management
Manager	S H Brown
Responsible Officer	S H Brown
Target Time	365 days
Service Standard Workflow History	2017

Create New Task		
New Task Type	Acknowledge request	200
Workflow Details		NC ¹

Workflow Details

Task name	Status	Opened	Target	Due	Closed	Outcome	Action Officer	Role	Delegating Officer	Role	Notes	Checklist	1
Acknowledge request	Complete	26/08/21 11:26 AM	2 days	30/08/21	26/08/21 11:30 AM	Completed	Prue Schofield	Infra - ISAT - Engineering			BRC acknowledgement emailed (P E Schofield - 26/08/2021)		
Investigate Respond Close 10	Complete	26/08/21 11:30 AM	10 days	09/09/21	07/09/21 02:04 PM	Completed	Benjamin Ulcoq	Technical Officer Corridor Management			BRC response emailed (P E Schofield - 07/09/2021)		
Information Only	Optional		10 days			X	2	Infra - ISAT - Engineering					

•				•
Street	Cedarview Lane	Suburb	SOUTH BINGERA Old Cedars Road	
Suburb	SOUTH BINGERA	Baldwins Road	Suburb	
SOUTH BINGERA	South Isis Road	Suburb	SOUTH ISIS	
Customer Details				
NAR Number	223297			
User	Ergon Energy Limited			
Address	PO Box 578 MORNINGSIDE QLD 4170			
Business Phone	Category A			
Email Address	admin@erds.com.au			

https://www.bundaberg-qld.altitudelg.com/i-services/dialog/crm/enquiryDetails.do?doc_acc=002.2021.00618985.001&doc_desc=Customer Request Management&doc_type=2

Attachments

Contact Method	Email			
Attachments		005		
Attachment Options	Clicking 'Attachment Options' will launch Authority	Document Central.		
Document ID	Document Date	Document Description	File Type	File Size
0A5963638	26/08/2021	Ergon Energy - WR1635352 Notification of Works - Various Locations South Isis.msg	MSG	0.0M
0A6003047	07/09/2021	BRC Response - 618985 - Baldwins Rd, South Bingera Road, Cedarview Lane and Old Cedar Road, South Bingera - Reference: WR1635352.msg	MSG	0.0M
0A6003049	07/09/2021	Approval Email - 618985 - Baldwins Rd, South Bingera Road, Cedarview Lane and Old Cedar Road, South Bingera - Reference: WR1635352.msg	MSG	0.0M

		×O
Stop the Press?	Ν	
Potential Insurance Claim	Ν	210/1
		Let
	500	
	eas	
R)	

Attachment 1 - A5963638

Jessica Cause

From:	Category A
Sent:	Thursday, 26 August 2021 9:45 AM
То:	Engineering
Subject:	20210826 D07898 WR1635352 Notification of Works
Attachments:	WR1635352 Form 229 - Written Agreement or Notification for Proposal Electrical Works on a Road.pdf; WR1635352_1 REV 0 - JZ Singed Off
	20210824.pdf
Follow Up Flag:	Follow up
Flag Status:	Completed
Catagorias	Druce
Categories:	Prue
	×O

Good morning

Please find attached Ergon Cover Letter and a copy of the ERDS Works Plan, outlining the proposed Ergon work to be carried out at South Bingera.

Ergon would appreciate if you could return your acceptance of this work to: admin@erds.com.au

If you have any queries, please don't hesitate to contact the office.

Kind regards



Category A Junior Project Manager

Phone: 07 3518 3100 | Category A Web: www.erds.com.au

Web: www.erus.com.au

Written Agreement or Notification for Proposed Electricity Works on a Road



In accordance with the provisions of the *Electricity Act 1994*, Energex or Ergon Energy proposes to carry out works on a road as shown on the attached works plan including associated clearing and vegetation triming as required.


Part A To be comp	bleted by Electricity Entity				
Works Request No.	WR1635352	Project No.	Constr	uction Start Date	16/12/2021
Date of Request	26/08/2021		Constr	uction Finish Date	16/06/2022
Street / Road Names	Baldwins Rd, South Bingera Roa	ad, Cedarview Lane & Old Ced	ar Road	(0
Suburbs / Locations	South Bingera			Å	V
Priority of Work	🛛 Normal 🛛 High			N	
Category of Work Typ	De			<u> </u>	
Maintenance	Overhead Electrical Works	Underground Electrical	Works	Civil works on F	ootpath/Roadway
New Works	Underground Electrical Work Overhead Electrical Works	s Civil works on Footpath	/Roadway	Install Streetligh	t Pole/s
Alignment of New Assets	Install on standard road reserved	rve alignment 🗌 Install on no	on-standard	l road reserve alignm	ent
Traffic Control Required	🛛 Yes 🗌 No	×O			
Comments or further description of works		d'h			
Requested By (Design	ners Details)				
Name	Category A	Lo	cation	Murarrie	
Phone No.	07 3518 3100				
Email Address	admin@erds.com.au				
Postal Address	PO Box 578, Morningside QLD 4	1170			
Authority / Council De	etails				
Authority / Council	Bundaberg Regional Council				
Title					
Attention	CEO	De	partment	Infrastructure	
Email Address	admin@erds.com.au	Of	fice	Bundaberg	

Written Agreement or Notification for Proposed Electricity Works on a Road




Part B Response by Authority / Council

As these works are associated with the provision or improvement of supply to our customers, Energex or a prompt reply to enable Ergon Energy/Energex to carry out its statutory duties.	Ergon Energy v	would appreciate	
Tick the relevant box and return (via email) to the designer's email address as shown above.			
☐ No Objection to the Proposal as outlined on the attached Works Plan Drawing No.	F or inclusi		
No Objection but Special Conditions are required - refer to attached conditions	For inclusion of conditions or objections, please attach to the return email		
Objection to Proposal - Further Information required		ie return eman	
Respond using this form or via the email to -	Č.	V	
Authority Representative	R A		
Contact Phone No.	Date	/ /	
Released under Right to Informatic			




w	1 N		2		3	4			5	6		7		8		9	
COORI	S RAL SITE DNIATES 24.9791 152.1828	3007009	3007008 9 46m 11	90 1RP7781 (1) (3007006) 85 2RP7781 3604	RP221361 2 3007005 614702 100 5 100 10763603 17 3RP896007	3 3007004	<u>-</u> 100	4 3007003 5 420 1042011 601531 60	2 Contraction		1 Minus SHEET 3 4	LAND P/ PROPER PROPER CONTA(AILS (SOURC	S: 60 BALWINS	/Α		IA.MC
					CONSTRUC	ION SCHEDULE -	SHEET 2 C	DF 4		AREA		CONTACT DETAILS (SO	URCE: QVAS	3RP896007		AGES.COM.AU):	
D STN			POLE SETTING	ACTION	CONSTRUCTION CLASS	CONSTRUCTION CODE	DRAWING NUMBER			REMARKS		PROPERTY OWN	[REBECCA MARSCHK DAWN WILLET	λE.		
1			DEPTH (m)	Upgrade	Cross Arm	11S3/27/B/FLU/R	1077	2	-	LU towards Pole 3007008.		PROPERTY ADD		17 BALDWINS RD SOUTH BINGERA, QI	LD 4670		
1				Upgrade Install	General Equipment Stay	11NBST3/2/PG7-PG7 PSW/11GS2/45SA	1328 1097		Bridge Position 1 APF As pegged 10.1m from	to Position 2 FLU. n base of Pole bearing 297 degrees.		CONTACT PHON	IE: (0420 285 893 (REBEC Category A	CCA)		
2	300700)5		Upgrade	Cross Arm	11DP3/20/FLU/R	1039	1				EMAIL:		rebeccamarschke6@g	mail com		
2				Upgrade Upgrade	General Equipment Cross Arm	SOHS/225 11DP3/20/FLU/R	1053 1039	1	Towards HSE60.						jinail.com		
3				Recover	Earth	EHVE	1132	2				MAILING ADDRE	00 I				
E 4				Upgrade	Cross Arm Stay	11S3/27/B/FLU/R PSW/11GS2/60SA	1077 1097	1 2	As neared 6 6m from	base of pole bearing 288 degrees.	L						
4				Install Upgrade	Cross Arm	LVT3/71/MOO	1097	3	Towards Pole 104201								
5				Upgrade	Cross Arm	11DP3/20/FLU/R	1039	1									
5 6				Upgrade Upgrade	Cross Arm Cross Arm	LVP3/70/MOO 11DP3/20/FLU/R	1017 1039	2									
6	30070	01		Upgrade	Cross Arm	LVT3/71/MOO	1019		Attach 2.4m below H	/ xarm and facing towards Pole 1042	0161.						
7			2.15	Install Install	Pole Cross Arm	WP14/8S/NE 11DP3/20/FLU/R	1091 1039	1	$\mathbf{\Theta}^{\mathbf{-}}$								
F 8	300700	00 Ex	2.15	Upgrade	Pole	WP14/8S/NE	1091	C									
8				Upgrade Upgrade	Cross Arm Pole Equipment	11SSW3/40/B/FLU/R SW11/3/SLS/X2/PG1	1186 1099	1									
8	300700	00		Install	Earth	EOP	1337	2									
101	1 107636	03		Install	Stay	PSW/11GS2/60SA	1097	2	As pegged 5.1m from	base of pole bearing 199 degrees.							
			OVERHEA		POUT	E - SHEET 2 OF 4	WIND			Olalia - N-		SAG TABLE			ro		
G ST		ACTION VOL			NUMBER OF ONDUCTORS	TH (m) % NBL PI	RESSURE	REMARK	is	Station No. From To	ge 5°C 10°	C 15°C 20°C 25°C		g (m) @ Temperatu C 40°C 45°C 50°		C 65°C 70°C	75°
1		Upgrade 1			3 302		(pa) 1200	Dwg. 172	5			0 0.63 0.66 0.69					
2				225	1 10	10 Service	1200	Dwg. 104	9								
4					3 247		1200	Dwg. 172 Dwg. 121									
4	6	Re-tension 4	15V M	00	4 99	50 10	1200	Re-Tension to 1									
					<u> </u>	LEGEND							REVI	ISION CONTROL			
NARY DESIG						planned shown in red, recovered in gre I NETWORK-SYS EARTH - 0/H				ER	12	Created E		Created Date: 2	25/08/2021		JRP(
MINAR I: E: 25/0					LV POLE N HV POLE	Y HV SWITCH O/H] SUB TRANSFORMER ► AER	LV CONDUCTOR			PROJECT NO: D07898						CORNER	OF B SO
PRELIMIN 0 DRN: DATE:					HV/LV POLE	H GROUND STAY				CERTIFICATION: JI ZHOU RPEQ No: 21630	Category A	5/08/2021 Checked B	By:Category A	Checked Date: 2	5/08/2021	RPX	K RNS
	_		2		3	4			5	6		7		8		9	—

10			11			12	
	ELE	CTRICAL	NOTE	<u>S</u>			
\sim	1.		NTAINE	D IN THE EF	NS REFERRED T RGON ENERGY C CATED.		N A
	2.	SERVICES SH BEFORE YOU	IALL BE DIG SEF	REQUESTE RVICE PRIO	DCATION OF EXIS D FROM THE QU R TO COMMENC M OF TWO DAYS	EENSLAND DI	AL
	3.	CHECK PHAS	ING PRI	OR TO COM	MISSIONING.		
	4.	CONFIRM LV	AND HV	SWITCHING	POINTS AND B	RIDGING	
	<u>C0</u>	NSTRUCT	ION N	OTES			В
		CONSTRUCTIO			NPLY WITH THE I	OLLOWING	
	•	DISTRIBUTION OVERHEAD C			NUAL.		
	SC	OPE OF W	ORKS				
	•	RECOVER 11			R.		с
	•		LES, CR	OSSARMS,	BRIDGING, & ST	AYS.	
	•	RECOVER EA RE-TENSION					
	•	INSTALL NEW UPGRADE 11			LL EARTHING.		
							D
							E
			[Г	
				CAU	TION		
					ON, & STRA		-
			U		UND ASSETS CINITY		
				LOCATION	S REQUIRED XCAVATING		
							F
]			MARK UP THIS		
			CHANG		TURN TO NETWO	ORK	
			CHANG	ES Yes/No			
1			NAME				
-			SIGNAT	URE			G
1		l]	0
					gn enquires pleas		
			LVE		act@ergon.com. include)	au	
		Subjec	t: Constru		WR1635352 Co	ontractor name	
			Drawing Status Preliminary Project :	s: Design	Contract / Quote	Number	Н
RD & SOUTH-B		ABN 50 087 646 062 RA RD	1635352	11			0
GERA, QLD 4670 D GV-F HV Baldw	ins Ro	ł	A3	ER TO BAR SCALE	635352_	ISS SH	SUE IEET
10			SCALE - REF	ER TU BAR SCALE		12	of 4



_		10		11	12	7
			ELECT	RICAL NOTES		
(GES.CO	M.AU):	PLAN		UCTIONS REFERRED TO ON THIS THE ERGON ENERGY CONSTRUCTION E INDICATED.	A
		9	SER' BEF(WOF	VICES SHALL BE REQU ORE YOU DIG SERVICE	ND LOCATION OF EXISTING JESTED FROM THE QUEENSLAND DIAL E PRIOR TO COMMENCEMENT OF INIMUM OF TWO DAYS NOTICE IS	
			3. CHE	CK PHASING PRIOR TO	COMMISSIONING.	
			4. CON	FIRM LV AND HV SWIT	CHING POINTS AND BRIDGING	
			CONST	RUCTION NOTE	S	B
(GES.CO	M.AU):		STRUCTION WORK IS T NERGY DOCUMENTS:	O COMPLY WITH THE FOLLOWING	
				RIBUTION DESIGN MA		
			SCOPE	OF WORKS		
			 UPG UPG UPG 	,	DR.	с
			 REC 	OVER STAY. INSTALL S OVER POLE & CROSSA	STAYS.	
	ON		INSTUPG	ALL POLE & CROSSAR RADE SERVICES. INST	MS.	
	, & A			RADE 11kV SWITCH. All New Midspan PC	DLE.	
١	RA D ASSE	ts				D
E	ITY QUIRED					
A	VATING					
S	HEET	Г 3 OF 4				\mid
-	MES (m)	% NBL	WIND PRESSURE (pa)	REMARKS		
	111	20	1200	Dwg. 1725		E
	167 173	20 20	1200 1200	Dwg. 1725 Dwg. 1725		
	173	20	1200	Dwg. 1725 Dwg. 1725		
	25	2.5	1200	Dwg. 1253		
-	9	Service	1200	Dwg. 1049		
_	11	Service	1200	Dwg. 1049		
						F
.(DETAILS (, CORELOGIC.COM.AU 8SP209693	, & WHITEPAGES.COM.AU):	
		OPERTY C	_	Category A		
	ייט	OPERTY A		17 SOUTH BINGERA RI		G
	۲R	UICRIYA		17 SOUTH BINGERA RI SOUTH BINGERA, QLD		
		NTACT PH		TBC		
		iail Niling add		Category A		
	MA					
				Drawing Status: Preliminary Design Project :	Contract / Quote Number	Н
J	TH BING	RD & SOU SERA, QLD	TH-BINGERA RE 4670	087 646 062 1635352	1635352_1 0 Issue	
_	ь BUND	0 GV-F HV I	Baldwins Rd	SCALE - REFER TO BA	CHEET	Г
		10	1	11	12	



	10			11		12	
		ELE	CTRICA	L NOTES			
	0)	PLAN ARE		JCTIONS REFERRE HE ERGON ENERG' INDICATED.		A
			Services Before yo	SHALL BE REQU DU DIG SERVICE HONE 1100 (A M	ND LOCATION OF E ESTED FROM THE (PRIOR TO COMMEI INIMUM OF TWO DA	QUEENSLAND DIAL	
		3.	CHECK PH	ASING PRIOR TO	COMMISSIONING.		
		4.	CONFIRM L	V AND HV SWIT	CHING POINTS AND	BRIDGING	
RK		CON	ISTRUC	TION NOTE	<u>S</u>		В
				TION WORK IS TO DOCUMENTS:	O COMPLY WITH TH	e following	
				ION DESIGN MAN CONSTRUCTIO			
		<u>SCC</u>	PE OF	WORKS			
email u htractor r	name	• • •	UPGRADE UPGRADE INSTALL ST RECOVER	AYS. POLE & CROSSA	DR. MS, BRIDGING, & S RMS.	TAYS.	с
	lane			DSPAN POLE & (LINE SPACERS)			
AGES.C	COM.AU):						D
							E
PAGES	.COM.AU):						
HL							F
SCHE	DULE - S	HEE	T 4 OF 4				G
R OF TORS	ROUTE LENGTH (m)	MES (m)	% NBL	WIND PRESSURE (pa)	REMARKS		
	228	228	22	1200	Dwg. 1233		-

ENERGY		Drawing Status: Preliminary Design					
ATION LTD A	BN 50 087 646 062	Project : Contract / Quote Num 1635352		uote Number			
DWINS RD & SOUTH-BINGEF H BINGERA, QLD 4670 B BUND GV-F HV Baldwins Rd	A3	16	635352	_1	0 ISSUE		
	SCALE - REFER TO BAR SCALE						
10					12		

Attachment 2 - A6003047

Jessica Cause

From:	Engineering
Sent:	Tuesday, 7 September 2021 2:02 PM
То:	admin@erds.com.au
Subject:	BRC Response - 618985 - Baldwins Rd, South Bingera Road, Cedarview Lane and Old Cedar Road, South Bingera - Reference: WR1635352
Attachments:	WR1635352 Form 229 - Written Agreement or Notification for Proposal Electrical Works on a Road.pdf

Attention: Category A

Dear Category A

Proposed Works - Baldwins Rd, South Bingera Road, Cedarview Lane and Old Cedar Road, South Bingera Your Reference: WR1635352

I refer to your enquiry dated 26 August 2021 forwarding details of the above works. I advise that Council offers no objection to the proposed work and that Council has no works currently planned for this location. Please find attached completed *Written Agreement or Notification for Proposed Electricity Works on a Road*.

Any work undertaken is subject to the following conditions:

- 1. All road closures, part road closures, traffic control and pedestrian diversion shall be carried out in accordance with the Manual of Uniform Traffic Control Devices, Part 3. In particular, preparation and implementation of Traffic Management Plans and Traffic Guidance Schemes are to be carried out by competent persons as defined in the MUTCD.
- 2. A Traffic Management Plan must be forwarded to Council *10 business days* prior to any works commencing if the proposed works require a full road/footpath closure.
- 3. You are to notify and apply to Council in writing where the works necessitate the removal or significant lopping of trees or vegetation on Council controlled land. On-site inspection and advice in relation to vegetation can be arranged through Council's Parks, Sport and Natural Areas Section.

- 4. You are required to contact the Department of Resources Vegetation Management Section, regarding the removal of vegetation within the road reserve.
- 5. All disturbed areas to be reinstated to the previous condition or better upon completion of work.
- 6. All new poles to be located in line with property boundaries and 3 metres from the property frontage, where possible, and to be installed no closer than 600 mm from the invert batter of the table drain. Poles are not to be placed in the invert on the road side of the table drain invert. All stays (new and replacement) are to be installed in a pedestrian-friendly manner. Council's Technical Officer Corridor Management is to be advised prior to the installation of new poles to confirm locations.
- 7. Council has underground infrastructure in these locations. Identification of these services is your responsibility.
- 8. Any damage to Council property caused during the proposed works shall be rectified at your expense. You shall notify Council promptly of the nature of the damage so that Council can effect the necessary repairs.
- 9. Consultation with adjacent Property owners must be carried out prior to commencement of any works.

bundabe

10. It should be noted that Cedars Road is under the control of the Department of Transport and Main Roads and their approval must be obtained prior to the commencement of work.

If you have any queries regarding this matter and for inspection on completion of the works, please contact Council's Technical Officer – Corridor Management, Ben Ulcoq on 1300 883 699, quoting **reference 618985** or email *engineering@bundaberg.qld.gov.au*.

Yours faithfully

BEN ULCOQ

Technical Officer – Corridor Management ENGINEERING SERVICES Infrastructure Services T 1300 883 699 E engineering@bundaberg.gld.gov.au



Written Agreement or Notification for Proposed Electricity Works on a Road



In accordance with the provisions of the *Electricity Act 1994*, Energex or Ergon Energy proposes to carry out works on a road as shown on the attached works plan including associated clearing and vegetation triming as required.

Part A To be comp	bleted by Electricity Entity				
Works Request No.	WR1635352	Project No.	Constr	uction Start Date	16/12/2021
Date of Request	26/08/2021		Constr	uction Finish Date	16/06/2022
Street / Road Names	Baldwins Rd, South Bingera Roa	ad, Cedarview Lane & Old Ced	ar Road	(0
Suburbs / Locations	South Bingera			Å	
Priority of Work	🛛 Normal 🛛 High			R	
Category of Work Typ	De			<u> </u>	
Maintenance	Overhead Electrical Works	Underground Electrical	Works	Civil works on F	ootpath/Roadway
New Works	Underground Electrical Work Overhead Electrical Works	s Civil works on Footpath	/Roadway	Install Streetligh	t Pole/s
Alignment of New Assets	Install on standard road reserved	rve alignment 🗌 Install on no	on-standard	l road reserve alignm	ent
Traffic Control Required	🖾 Yes 🗌 No	×O			
Comments or further description of works		d'h			
Requested By (Design	ners Details)				
Name	Category A	Lo	cation	Murarrie	
Phone No.	07 3518 3100				
Email Address	admin@erds.com.au				
Postal Address	PO Box 578, Morningside QLD 4	1170			
Authority / Council Details					
Authority / Council	Bundaberg Regional Council				
Title					
Attention	CEO	De	partment	Infrastructure	
Email Address	admin@erds.com.au	Of	fice	Bundaberg	

Written Agreement or Notification for Proposed Electricity Works on a Road



Part B Response by Authority / Council

As these works are associated with the provision or improvement of supply to our customers, Energex or Ergon Energy would appreciate a prompt reply to enable Ergon Energy/Energex to carry out its statutory duties.

Tick the relevant box and return (via email) to the designer's email address as shown above.

□ No Objection to the Proposal as outlined on the attached Works Plan Drawing No.

No Objection but Special Conditions are required - refer to attached conditions

Objection to Proposal - Further Information required

Respond using this form or via the email to - engineering@bundaberg.qld.gov.au

Authority Representative Ben Ulcoq (Technical Officer - Corridor Management)

Released under Right to Informa **Contact Phone No.** 1300 883 699

For inclusion of conditions or objections, please attach to the return email

Date 07 / 09 / 2021

Attachment 3 - A6003049

Jessica Cause

From:	Benjamin Ulcoq
Sent:	Friday, 3 September 2021 11:45 AM
То:	Engineering
Subject:	BRC Response - CRM 618985 - Due Date - 09.09.21 - <copy and="" both="" email<="" in="" lines="" paste="" subject="" th=""></copy>

Categories:

Prue

CRM Details: Written Agreement for Proposed Works - Ergon - ERDS - WR1635352 - Baldwins Road, South Bingera Road, Cedarview Lane and Old Cedar Road, South Isis

Admin, approval is given to please process email to the Ergon subcontractor with the following paragraphs, and complete the Written Agreement Form by selecting the checkbox: "*No Objection but Special Conditions are Required – refer to attached conditions*', complete my name as Authority Representative, Contact Phone No: 1300 883 699 and Date processed:

h. .

Paragraphs.	
1.	
2.	
3.	
4.	
6.	
7.	
9.	
10.	
11. Property Owners.	
12. Cedars Road.	
Regards	
Ben Ulcoq.	
	1

Admin to complete

SEND FROM ENGINEERING - COMPLETE HIGHLIGHTED AREAS COMPLETE AND ATTACH WRITTEN AGREEMENT – Tick 'No Objection but Special Conditions are Required – refer to attached conditions' box

– DELETE THIS LINE AND HIGHLIGHT WHEN COMPLETED

Attention: <<u><<Name>></u> <<Subcontractor Company>>

Dear <<Name>>

Ergon Energy - Proposed Works - [property address npc] Your Reference: <<u><<your reference>></u>

I refer to your enquiry dated << date correspondence received >> forwarding details of the above works. I advise that Council offers no objection to the proposed work on behalf of Ergon Energy and that Council has no works currently planned for this location. Please find attached completed *Written Agreement or Notification for Proposed Electricity Works on a Road*.

Any work undertaken is subject to the following conditions:

- 1. All road closures, part road closures, traffic control and pedestrian diversion shall be carried out in accordance with the Manual of Uniform Traffic Control Devices, Part 3. In particular, preparation and implementation of Traffic Management Plans and Traffic Guidance Schemes are to be carried out by competent persons as defined in the MUTCD.
- 2. A Traffic Management Plan must be forwarded to Council *10 business days* prior to any works commencing if the proposed works require a full road/footpath closure.
- 3. You are to notify and apply to Council in writing where the works necessitate the removal or significant lopping of trees or vegetation on Council controlled land. On-site inspection and advice in relation to vegetation can be arranged through Council's Parks, Sport and Natural Areas Section.
- 4. You are required to contact the Department of Resources Vegetation Management Section, regarding the removal of vegetation within the road reserve.

- 5. Conduits to be installed within 1.5 metres of the adjacent property boundary. Trenching is to be carried out on grassed areas only, i.e. driveway accesses and roadways are to be bored.
- 6. All disturbed areas to be reinstated to the previous condition or better upon completion of work.
- 7. All new poles to be located in line with property boundaries and 3 metres from the property frontage, where possible, and to be installed no closer than 600 mm from the invert batter of the table drain. Poles are not to be placed in the invert on the road side of the table drain invert. All stays (new and replacement) are to be installed in a pedestrian-friendly manner. Council's Technical Officer Corridor Management is to be advised prior to the installation of new poles to confirm locations.
- 8. All new poles to be located in line with property boundaries and within 600 mm of the back of the kerb and channel where possible. All stays (new and replacement) are to be installed in a pedestrian-friendly manner. Council's Technical Officer Corridor Management is to be advised prior to installation of new poles to confirm locations.
- 9. Council has underground infrastructure in these locations. Identification of these services is your responsibility.
- 10. Any damage to Council property caused during the proposed works shall be rectified at your expense. You shall notify Council promptly of the nature of the damage so that Council can effect the necessary repairs.
- 11. Consultation with adjacent <

 business/property>> owners must be carried out prior to commencement of any works.
- 12. It should be noted that [Road/Street] is under the control of the Department of Transport and Main Roads and their approval must be obtained prior to the commencement of work.

If you have any queries regarding this matter and for inspection on completion of the works, please contact Council's Technical Officer – Corridor Management,

Yours faithfully

APPLY APPROVAL OFFICER'S OUTLOOK SIGNATURE

01025